

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1740	(347/104).OCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/07/09 16:17
L2	70154	charg\$3 and (neutral) and resistance	US-PGPUB; USPAT; USOCR	OR	ON	2009/07/09 16:17
L3	1	L2 and L1	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/07/09 16:17
L4	101305	(("347") or ("399")).CLAS.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/07/09 16:18
L5	1094	L2 and L4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:18
L6	1094	L5 and (resist\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:19
L7	11	L5 and ((resist\$4) near (measuring or measurement or measure))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:20
L8	8	((convey\$4) and charg\$3 and ((resist \$4) near (measuring or measurement or measure))).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:25
L9	28	((convey\$4) and charg\$3 and ((resist \$4) same (measuring or measurement or measure))).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:26

L10	29	((convey\$4) and charg\$3 and ((resist \$4) same (measuring or measurement or measure))).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/07/09 16:27
L11	1	"10563214"	US-PGPUB; USPAT; USOCR	OR	OFF	2009/07/09 16:28
L12	14	((convey\$4) and charg\$3 and ((resist \$4) near (measuring or measurement or measure or detect \$3))).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:30
L13	14	((convey\$4) and charg\$3 and ((measuring or measurement or measure or detect \$3) near (resist \$4))).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:31
L14	65	((convey\$4) and charg\$3 and ((measuring or measurement or measure or detect \$3) same (resist \$4))).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:31
L15	6	((convey\$4) and (charg\$3 same (positive or negative)) and ((measuring or measurement or measure or detect \$3) same (resist \$4))).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:32
L16	19	L12 or L15	US-PGPUB; USPAT; USOCR	OR	OFF	2009/07/09 16:33

7/9/2009 5:02:06 PM

C:\Documents and Settings\jzimmermann\My Documents\EAST\Workspaces\10563214.wsp